### Maryland Historical Trust

Maryland Inventory of Historic Properties number:	661
Name: Story Lawrover N	$\cup$
The bridge referenced herein was inventoried by the Maryland S Historic Bridge Inventory, and SHA provided the Trust with elig The Trust accepted the Historic Bridge Inventory on April 3, 20 determination of eligibility.	gibility determinations in February 2001.
MARYLAND HISTORICA	L TRUST
Flioibility Recommended	Eligibility Not RecommendedA
Eligibility Recommended  Criteria:ABCD Considerations:A	
Criteria:ABCD Considerations:A	

cking

# MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT N	Vo.	HO-661

SHA Bridge No. HO 32 Br	idge name <u>Shady Lane</u>		
LOCATION: Street/Road name and number [fac	cility carried] Shady La	ne over Dorsey Branch	
City/town Glenwood		Vicin	ity X
County Howard			
This bridge projects over: Road	Railway	Water X La	und
Ownership: State	County X	Municipal	Other
HISTORIC STATUS: Is the bridge located within a desig National Register-listed di Locally-designated district	strict Natio	nal Register-determin	No <u>X</u> ed-eligible district
Name of district		<del></del> -	
BRIDGE TYPE: Timber Bridge Beam Bridge	Truss -Covered	Trestle Ti	mber-And-Concrete
Stone Arch Bridge			
Metal Truss Bridge			
Movable Bridge:	Provide C'ast Y		
Swing Vertical Lift	Bascule Single La Retractile		Multiple Leaf
Metal Girder X  Rolled Girder X  Plate Girder		oncrete Encased	
Metal Suspension			<del></del>
Metal Arch			
Metal Cantilever			
Concrete:			
Concrete Arch Type N	Concrete Slab	Concrete Beam	Rigid Frame

Ho-661

DESCRIPTION: Setting: Urban Small town Rural X
Describe Setting:
Bridge HO 32 carries Shady Lane over Dorsey Branch in Howard County, Maryland. Shady Lane runs in a generally north-south direction at this location; Dorsey Branch runs generally east-west. The bridge is located in a rural area, with a wooded channel bank and open fields. There are two modern twentieth century domestic structures in view from the bridge.
Describe Superstructure and Substructure:
The superstructure of Bridge HO 32 is a single 22 foot 5 inch span steel beam with a corrugated metal deck, and a total length of 25 feet. It also has a standard W-beam guardrail and a bituminous concrete wearing surface. The substructure consists of concrete abutments and wingwalls.
Discuss Major Alterations:
There is no obvious indication of major alterations made to Ho 32. However, the 1995 inspection report indicates that this structure is in good condition and not in need of major repairs. The inspection report suggests superficial modifications such as cleaning and painting. The current condition of the bridge would indicate that alterations, possible beam and/or deck replacement and abutment repair, have been made since the bridge's original construction in the 1930s. It is probable that these repairs and changes would have occurred between the mid-1970s and the early 1980s, when many similar bridges in Howard County were being rehabilitated. A conversation with a county bridge engineer indicates that it is highly likely that some if not all of the steel beams were replaced. The deck was replaced and the abutments were cleaned and patched in a rehab episode between 1980 and 1985, however; there is no documentary evidence to confirm this.
HISTORY:
WHEN was the bridge built: 1935  This date is: Actual Estimated X  Source of date: Plaque Design plans County bridge files/inspection formX Other (specify):
WHY was the bridge built?
The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.
WHO was the designer?
Unknown
WHO was the builder? Unknown
WHY was the bridge altered?
The bridge was altered to ensure its structural integrity.
Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

HO-661

#### **SURVEYOR/HISTORIAN ANALYSIS:**

This bridge may have National	onal Register significance for its association with:
A - Events	B- Person
C- Engineering/are	chitectural character

The bridge does not have National Register significance.

Was the bridge constructed in response to significant events in Maryland or local history?

Many less stable timber or stone bridges were replaced with steel beam bridges during the early part of the twentieth century. Other than being a typical replacement of the time period, it is not likely that HO 32 was constructed in response to any specific events in Maryland or local history.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

No, this structure is not a significant example of its type. The good condition of the present structure suggests that the structure has had significant repairs, therefore placing its integrity in doubt.

Does the bridge retain integrity of important elements described in Context Addendum?

The rolled wide flange beams are considered primary character defining elements. According to the 1995 inspection report they are in good condition, which would indicate that they have been replaced fairly recently. The same can be said for the bridge deck, which is considered a secondary character defining element, and the concrete abutments, which are considered a primary character defining element.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

While the structure is a typical example of bridge construction in the 1930s, it is not a significant example of a particular manufacturer, designer, or engineer.

Should the bridge he given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

#### **BIBLIOGRAPHY:**

**Howard County** 

v.d. Bridge Inspection Files

Greiner, Inc.

1995 Historic Bridge Inventory Form.

HO-661

P.A.C. Spero & Company and Louis Berger & Associates 1995 Historic Bridges in Maryland: Historic Bridge Context.

Surveyor:

Name: Stephanie L. Bandy Date: August 1995

Organization: State Highway Administration Telephone: (410) 321-2213

Address: 2323 West Joppa Road, Brooklandville, MD 21002

Revised by P.A.C. Spero & Company, April 1998

## INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM


Property/District Name: <u>Bridge HO-32</u>	Survey Number: HO-661
Project: Bridge Replacement	Agency: FHWA
Site visit by MHT Staff: X no yes Name	Date
Eligibility recommended Eligibility not recomm	mended <u>X</u>
Criteria:ABCD Considerations:AI	BCDEFGNone
Justification for decision: (Use continuation sheet if ne	ecessary and attach map)
Bridge HO-32 is located in a rural area and carries Shady County, Maryland. The bridge was included in the His determined not eligible for listing on the National Req Interagency Bridge Committee.	storic Bridge Inventory and was
Bridge HO-32 is a single-span steel beam structure with a length of 25 feet. The substructure consists of concrete standard W-beam guard rail and a bituminous concrete wear:	abutments and wing walls. It has
The bridge was built in 1935 and was rehabilitated, probalis not a significant example of its type and has lost its in the bridge thus does not meet Criterion C of the Register. Example of a particular manufacturer, designer or engineer Criterion B. The property is not known to have any associour past and thus does not qualify under Criterion A.	ntegrity due to major alterations. The bridge is not a significant , and thus does not qualify under
Documentation on the property/district is present	ced in: <u>Review and Compliance</u>
Prepared by: <u>Department of Public Works</u>	
Kimberly Prothro Williams March Reviewer, Office of Preservation Services	20, 1997 Date
NR program concurrence: X yes no not applical	Date

Shop

Survey	No.	HO-661

#### MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

I.	Geographic Region:	
_	Eastern Shore Western Shore	(all Eastern Shore counties, and Cecil) (Anne Arundel, Calvert, Charles,
<u> </u>	Piedmont	Prince George's and St. Mary's) (Baltimore City, Baltimore, Carroll, Frederick, Harford, Howard, Montgomery)
	Western Maryland	(Allegany, Garrett and Washington)
II.	Chronological/Developmental Pe	riods:
	Paleo-Indian Early Archaic Middle Archaic Late Archaic Early Woodland Middle Woodland Late Woodland/Archaic Contact and Settlement Rural Agrarian Intensification Agricultural-Industrial Transi Industrial/Urban Dominance Modern Period Unknown Period ( prehistor	A.D. 1815-1870 A.D. 1870-1930 A.D. 1930-Present
III.	Prehistoric Period Themes:	IV. Historic Period Themes:
	Subsistence Settlement  Political Demographic Religion Technology Environmental Adaptation	Agriculture Architecture, Landscape Architecture, and Community Planning Economic (Commercial and Industrial) Government/Law Military Religion Social/Educational/Cultural Transportation
V. R	esource Type:	
	Category: <u>Structure</u>	
	Historic Environment: Rural	
	Historic Function(s) and Use(s	): <u>Bridge</u>
		·····
		· · · · · · · · · · · · · · · · · · ·
	Known Design Source:	





HO	-66
	HO

Name <u>103</u> 2	2-SHROW LAWE OVER DORSEN BRANCH
County/State	Howard/MD
Name of Pho	otographer DAVID DIEHL
Date 20	15
1	
Location of	Negative 5HA
Description	NORTH APPROACH LOOKING SOUTH
Î	
1	4
Number 28	0f3



10	-le	6	
	10	10-le	10-66

Name 4032 - SHADY LADOF DNERDORSEY BRATOCH
County/State Howard / mo
Name of Photographer DAVID DIENL
Date 2 95
Location of Negative SHR
Description South APPROACH LOOKING NORTH

1 4 Number 24 of 3

# 5° CY



Inventory # HO -661	
Name 10032 - SHADY LANE OVER DORSEY BRAINCH	A
County/State Howard / MD	

Name of Photographer DAVID DIENL Date 2 95

Location of Negative SHA

Description EAST ELEVATION LOOKING WAST

3 4 Number 3 of 3



## Inventory # Ho-lole |

County/State HOWARD [MD]  Name of Photographer ORVID OIEHL  Date 2/95  Location of Negative SHA  Description WEST ELEVATION LOOKANG EAST	Name 4032 - SHADY LANE OVER DRSKY BRANCH
Date 2/95  Location of Negative SHA  Description WEST ELEVATION LOCKING EAST	County/State HOWARD / MO
Location of Negative SHA  Description WEST ELEVATION LOCKWOO EAST  4	Name of Photographer ORVID OIERL
Description WEST ELEVATION LOOKING EAST  4	Date 2 95
4 4	Location of Negative SHA
4 4	Description WEST ELEVATION LEGILING EAST
4 4	
Number 3/ of 2)	Number 3+ of 3+